

Pressure Transmitter

Selection	Value
ID number	
Number of Channels	
Channel input	
Max Gross weight	
Type	



Pressure Transmitter - Transducer

Pressure transmitters can be supplied for reading vacuum or pressure.

We can supply pressure readers for pressures up to 10000 psi



English



The pressure reader needs a logging device that can convert the signal from milliamperes to bar or psi, often a pressure curve showing start pressure and end pressure is also desired.

A logger with associated software performs this, at the same time often measuring temperature and time for the reading period.

There are a number of pressure loggers available, we recommend PT Logger.

This produces a report based on the requirements referred to in DNV-OS

Contact us for more information and assistance.



English

